

Details of Registered Business

Gas Safe Register No _____
 Registered Engineer's Name S. Robinson
 Gas Safe Register Licence Number 519655
 Business A&R Plumbing
 Address 71 Church Lane
 Postcode TS6 0JH
 Contact No _____

Details of Site

Name (Mr/Mrs/Miss/MS) _____
 Address 63 Everett
 Postcode _____
 Contact No _____

Details of Customer/Landlord (or agent where appropriate)

Name (Mr/Mrs/Miss/MS) _____
 Address _____
 Postcode _____
 Contact No _____

Number of Appliances tested

Outcome of gas installation pipework visual inspection?
 Outcome of gas supply pipework visual inspection?
 Is the Emergency Control Valve access satisfactory?
 Outcome of gas tightness test?
 Is the Protective Equipotential bonding satisfactory?

select as appropriate and relevant

Pass / Fail / NA
 Pass / Fail / NA
 Pass / Fail / NA
 Pass / Fail / NA
 Pass / Fail / NA

Appliance Details

	Location of	Type	Manufacturer	Model	Serial Number (if required)	Owned by Landlord/Owner? (Yes/No)	Inspected (Yes/No)	Type of flue
1	Kitchen	Contra	Localic	Portline	HEATLINE	Yes	Yes	BS
2	Bathroom	Contra				Yes	Yes	BS
3								
4								

Inspection Details

	Operating pressure in mbar and/ or heat input kW/h or Btu/h	Operation of safety device(s)	Ventilation satisfactory	Visual condition of flue and termination	Flue operation checks	Combustion analyser reading (if applicable)	Appliance serviced	CO Alarm fitted	CO Alarm tested (if fitted)	SAFE TO USE
1		Pass/Fail/NA	Yes/No	Pass/Fail/NA	Pass/Fail/NA		Yes/No	Yes/No	Pass/Fail/NA	Yes/No
2	26kW	Pass	Yes	Pass	Pass	0.0068	Yes	Yes	Pass	Yes
3										
4										

Safety Related Defect(s) Identified

	GLSP classification eg. AR, ID	Warning/Advisory Record report form serial No'
1		
2		
3		
4		

Remedial Action Taken numbering should correspond to defects above.

1	
2	
3	
4	

Details of Work carried out

Record issued by: Signature S. Robinson
 Print Name S. Robinson
 Received by: Signature _____
 Date appliance(s)/flue(s) checked 7.8.23

* Refer to separate Warning Advisory Record

ATTENTION

Next safety check due by:

7.8.24